



Drive adapter


Standard configurations and machine specific executions upon request



Milling receptacle $\varnothing 16_{h6} \times 10$



Milling receptacle
spindle turning direction opposite
to drive turning direction



Trouble contour $\varnothing 138\text{mm}$