


Drive adapter


Standard configurations and machine specific executions upon request



For the perfect performance of the spindle it is important that the dust extraction in the tool cutting area works best possible!

Note

- For 1-sided edge processing engine without spindle Rotation axis
- For multipage edging motor spindle with Rotation axis is required



Collet receptacle Hi-Q/ER40

